

Fort Meade, MD Army Barracks

The Challenge: The barracks was covered with mold. The air system for the barracks had design flaws, which resulted in high amounts of condensation throughout the barracks. The system needed to be renovated and the mold in the barracks cleaned up.



The Solution: Benefect Disinfectant was chosen to clean all of the walls, furniture, floors, and interstitial areas in the ceiling plenum. The FiberTech F-50 primer and F-51MR mold resistant sealer coat were used to provide long-term protection against mold re-growth.

